

















Note: All modes and antennas had been tested, but only the worst data was recorded in the report.

11.8. APPENDIX G: FREQUENCY STABILITY

11.8.1. Test Result

Frequency Error vs. Voltage									
802.11ax HE20: 6195 MHz									
Temp.	Volt.	0 Minute		2 Minute		5 Minute		10 Minute	
		Freq.Error (MHz)	Tolerance (ppm)	Freq.Error (MHz)	Tolerance (ppm)	Freq.Error (MHz)	Tolerance (ppm)	Freq.Error (MHz)	Tolerance (ppm)
TN	VL	6194.9998	-0.03	6195.0189	3.06	6194.9883	-1.89	6195.0030	0.48
TN	VN	6194.9760	-3.88	6194.9851	-2.40	6195.0114	1.84	6194.9974	-0.42
TN	VH	6194.9950	-0.81	6194.9795	-3.31	6195.0231	3.73	6194.9854	-2.35
Frequency Error vs. Temperature									
802.11ax HE20: 6195 MHz									
Temp.	Volt.	0 Minute		2 Minute		5 Minute		10 Minute	
		Freq.Error (MHz)	Tolerance (ppm)	Freq.Error (MHz)	Tolerance (ppm)	Freq.Error (MHz)	Tolerance (ppm)	Freq.Error (MHz)	Tolerance (ppm)
40	VN	6194.9987	-0.20	6194.9949	-0.83	6195.0189	3.05	6194.9837	-2.63
30	VN	6194.9795	-3.31	6194.9927	-1.18	6194.9994	-0.09	6195.0183	2.95
20	VN	6195.0104	1.67	6195.0112	1.80	6194.9762	-3.85	6195.0009	0.15
10	VN	6194.9825	-2.83	6195.0106	1.72	6194.9891	-1.75	6194.9788	-3.42
0	VN	6194.9794	-3.33	6195.0182	2.94	6194.9960	-0.65	6194.9934	-1.06

Frequency Error vs. Voltage									
802.11ax HE20: 6995 MHz									
Temp.	Volt.	0 Minute		2 Minute		5 Minute		10 Minute	
		Freq.Error (MHz)	Tolerance (ppm)	Freq.Error (MHz)	Tolerance (ppm)	Freq.Error (MHz)	Tolerance (ppm)	Freq.Error (MHz)	Tolerance (ppm)
TN	VL	6994.9879	-1.73	6995.0138	1.97	6994.9901	-1.42	6994.9857	-2.05
TN	VN	6995.0206	2.95	6994.9854	-2.09	6995.0165	2.37	6995.0228	3.25
TN	VH	6994.9929	-1.02	6994.9824	-2.51	6995.0049	0.70	6994.9883	-1.67
Frequency Error vs. Temperature									
802.11ax HE20: 6995 MHz									
Temp.	Volt.	0 Minute		2 Minute		5 Minute		10 Minute	
		Freq.Error (MHz)	Tolerance (ppm)	Freq.Error (MHz)	Tolerance (ppm)	Freq.Error (MHz)	Tolerance (ppm)	Freq.Error (MHz)	Tolerance (ppm)
40	VN	6995.0090	1.29	6995.0148	2.12	6995.0170	2.43	6994.9890	-1.58
30	VN	6994.9976	-0.34	6995.0019	0.27	6994.9768	-3.32	6995.0006	0.09
20	VN	6995.0107	1.52	6995.0239	3.42	6994.9996	-0.05	6995.0116	1.66
10	VN	6994.9977	-0.33	6995.0233	3.32	6994.9752	-3.55	6994.9961	-0.56
0	VN	6995.0211	3.02	6994.9850	-2.15	6995.0227	3.24	6994.9823	-2.53

Note:

1. All antennas and test modes have been tested, only the worst data record in the report.
2. For the detail Test Conditions, please refer to section 7.6.

END OF REPORT